

Odds and Ends

- Fuel handlers, stay alert when fueling. The HEMTT driver will signal when it's time to shut off the fuel.
- . If you handle fuel at night, remember two things:
 - √ Wear goggles with a clear lens, not a sunglass or tinted lens.
 - √ The driver needs an explosion-proof flashlight or a chemlight to signal the fueler
 when to shut off the fuel.
- The fuel tank has an EMERGENCY FUEL SHUT OFF control. It's on the driver's side of the HEMTT. Pulling the control cuts off the flow of fuel. Every Soldier working near the truck needs to know where the control is—and how to use it.



 Federal regulations call for the use of hazardous materials placards when hauling hazardous cargo. That includes JP-8 fuel. Label your tanker with the right 4-digit class 3 Department of Transportation placards for flammable liquids.





• If a thunderstorm approaches or you see lightning, shut down fueling.




PS 708 49

Fire Extinguishers


ALWAYS
KEEP A HANDHELD FIRE
EXTINGUISHER
NEARBY-ABOUT
AN ARM'S
LENGTH AWAY,

IF A FIRE BREAKS OUT, YOU CAN'T AFFORD EXTRA STEPS RUNNING FOR HELP,

THE -10 TMS
NAME THREE
PRY CHEMICAL
EXTINGLISHERS...



 NSN 4210-01-133-9053. This is also a BII and it is mounted in the cabin to the right of the driver's seat.



 NSN 4210-00-965-1108. It's found on the Additional Authorization List and has a recommended quantity of four.

Sources of Ignition

IN ALMOST
ALL CASES,
FIRES AND
EXPLOSIONS
NEED AN
OLITSIDE
IGNITION
SOURCE

IN ALMOST
ARE
SOME
COMMON
SOURCES,
OUTSIDE
DON'T

TO GET

STARTED

DON'T LET THEM NEAR YOU WHEN YOU'RE HANDLING

FUEL.



Smoking, matches, cigarette lighters and open flames.

Friction between metals or other hard substances.
 They can cause sparks.

 Electrical equipment and wires. They can produce arcs or sparks. They can also produce heat. Make sure all electrical equipment in the area—generators, lights, power tools and extension cords—is explosion proof. Static electricity. Assume it's always there and take precautions. Bond and ground your vehicle before handling fuel.

 Welding, soldering, drilling or grinding They produce sparks and heat.



- Cutting torches.
- Jewelry that might spark against metal.
- There is one case when fires can start without an outside ignition source. It happens when rags or waste are soaked in varnish, linseed oil, paint or paint dryers. They can ignite on their own.



Higher Education

IF YOU WANT TO BECOME AN EXPERT FUEL HANDLER, READ YOUR 10 TMS, ESPECIALLY THESE PARTS...

- Warnings, and Warning Icons and
 Descriptions near the front of the TM.
 - Chap 1, Table 4, Significant Hazard and Safety Recommendations.
 - Work packages related to fueling
 operations in Chap 2, Operator Instructions.
 - Chap 4, Before and During PMCS.

IF YOU WANT TO PURSUE A PH.P. IN FUEL HANDLING, YOU MUST REAP FM 10-67-1, CONCEPTS AND EQUIPMENT OF PETROLEUM OPERATIONS.



YOU'LL FIND IT ON THE ARMY PUBLISHING DIRECTORATE (APD) WEBSITE: http://www.apd.army.mil/



PAY
PARTICULAR
ATTENTION
TO CHAP
2, SAFETY,
HEALTH AND
FIRE FIGHTING.

PS 708 51 NOV 11